

# RESISTANCE THERMOMETERS

## RTD 601

Mineral insulated resistance thermometer with bare connection ends

RTD:	Pt 100 acc. to DIN EN 60751
sheath material:	mat. no. 1.4541
measuring range:	-50 up to +400°C and -50 up to +600°C



### RTD:

- 1 x Pt 100 class B
- 1 x Pt 100 class A
- 2 x Pt 100 class B
- 2 x Pt 100 class A

### CIRCUIT OF INNER WIRES:

- 2-wire circuit
- 3-wire circuit
- 4-wire circuit

### SHEATH - Ø:

- 1,5 mm
- 3,0 mm
- 4,5 mm
- 6,0 mm
- other sheath-Ø \_\_\_\_\_

### TYPE OF CONNECTION WIRES:

- bare ends L=25mm
- bare ends L=40mm
- other cable ends \_\_\_\_\_
- bare ends L=50mm
- bare ends L=60mm

### ACCESSORIES (FIX):

- without
- with accessories \_\_\_\_\_

### MEASURING RANGE:

- 50 up to +400°C
- 50 up to +600°C
- other measuring range \_\_\_\_\_

NOMINAL LENGTH: \_\_\_\_\_ mm



Sheath-ø: 1,5 mm  
on request